

## PIP-II IT HWR - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
25131	Task	New	Normal	ACNET Parameters when changed must set off an alarm to indicate values have been changed.		10/27/2020 09:25 AM
24896	Task	New	Normal	HWR GDR Mode Turn-On procedure and sotware changes	Shrividyaa Sankar Raman	09/01/2020 03:07 PM
24880	Task	New	Normal	Data capture of Frequency error data for HWR Cavities	John Dusatko	08/28/2020 05:18 AM
24865	Task	Closed	Normal	Reference Magnitude and Phase Waveforms in Labview	Shrividyaa Sankar Raman	10/05/2020 09:51 AM
24845	Task	Closed	Normal	HWR Helix Cable Connector Issues	Daniel Klepec	08/31/2020 10:53 AM
24775	Task	New	Normal	Priorities for HWR		08/31/2020 11:41 AM
24772	Task	Resolved	Normal	Cavity 6 drive cable	Daniel Klepec	08/13/2020 01:23 PM
24754	Task	Resolved	Urgent	Remove & Repair HWR Pressure loop Signal conditioning chassis	Daniel Klepec	08/13/2020 01:28 PM
24734	Task	Resolved	Normal	Documenting recent software changes for resonance control and other upgrades	Shrividyaa Sankar Raman	01/27/2021 12:07 PM
24605	Task	Closed	Normal	Adding new waveform for Tuner Control Output	Shrividyaa Sankar Raman	10/05/2020 08:34 AM
24597	Task	Work in progress	Normal	Resonance controller needs diagnostics	Philip Varghese	07/10/2020 11:56 AM
24587	Task	Resolved	High	HWR start trigger cable termination	Daniel Klepec	07/02/2020 08:24 AM
24585	Task	Resolved	High	HWR resonance control pressure set button is broken	Daniel Klepec	07/02/2020 08:04 AM
24584	Task	New	Urgent	HWR startup procedure	Philip Varghese	07/01/2020 09:59 AM
24580	Task	Closed	Urgent	Spreadsheet to Dennis Nicklaus for HWR and SSR1	Shrividyaa Sankar Raman	07/01/2020 03:14 PM
24578	Task	Resolved	High	ACNET Connection	Shrividyaa Sankar Raman	01/27/2021 12:05 PM
24534	Task	New	Normal	HWR LLRF System Testing	Philip Varghese	06/19/2020 02:16 PM
24523	Task	Resolved	Normal	HWR 8 Channel Signal Conditioning Chassis	Daniel Klepec	08/07/2020 03:24 PM
23959	Task	New	High	HWR Resonance control system	Philip Varghese	02/16/2020 11:05 PM
23896	Task	New	Normal	Argonne Resonance Controller Troubleshooting & Modifications		01/15/2020 11:44 AM
23591	Task	Closed	Normal	LabVIEW creation for HWR	Shrividyaa Sankar Raman	07/07/2020 08:34 AM
23590	Task	Resolved	Normal	SSR1 Testing	Shrividyaa Sankar Raman	01/27/2021 12:00 PM
23589	Task	Resolved	Normal	HWR Software Development and Testing	Shrividyaa Sankar Raman	01/27/2021 11:59 AM
23588	Task	New	High	Develop the requirements traceability spreadsheet	Brian Chase	11/12/2019 02:45 PM
23587	Task	Closed	Normal	Terminate cables for HWR valves and pressure transducers	Daniel Klepec	07/10/2020 07:49 AM
23586	Task	Resolved	High	Buy connectors and for connections between HWR and Resonance control chassis.	Shrividyaa Sankar Raman	01/27/2021 11:58 AM