

uBoone Operations - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
9077	Bug	Closed	Normal	Remove DAQ status from alarm tree temporarily	Glenn Horton-Smith	06/09/2015 09:47 AM
9048	Bug	Closed	Normal	Remove spare TPC PS LV channels from the Alarm system	Glenn Horton-Smith	10/02/2015 02:40 PM
9038	Bug	Closed	Normal	Relax Major/Minor low alarm for calibration channels to 0.4A instead of 0.5A	Glenn Horton-Smith	06/05/2015 10:14 PM
9037	Bug	Closed	Normal	Relax the MINOR High/low alarm range on TPCPS LV modules 1 through 6	Glenn Horton-Smith	06/05/2015 10:14 PM
9036	Bug	New	Normal	update the /home/uboone/daq/ directory on glomation-sbc-4	Sowjanya Gollapinni	06/04/2015 12:01 AM
9035	Bug	Closed	Normal	remove non-existent rack air temperature variables from EPICS DB	Glenn Horton-Smith	06/05/2015 10:13 PM
9023	Bug	New	High	investigate high Wiener internal temperatures in PL508 (CrateRails) supplies	Sowjanya Gollapinni	06/03/2015 11:47 AM
9021	Bug	Closed	Normal	Remove non-existent fan pack from slow controls for ELIZabeth and TPC5 racks	Glenn Horton-Smith	06/05/2015 10:12 PM
8990	Bug	Closed	Normal	Cannot acknowledge alarms after update to new version of control system gui	Glenn Horton-Smith	06/01/2015 10:51 AM
8989	Bug	Closed	Normal	Archived data not shown on rack fan speed and temperature panels	Glenn Horton-Smith	06/01/2015 10:52 AM
8915	Bug	Closed	Normal	Time on redmine server	Michael Kirby	06/05/2015 07:46 AM
8740	Bug	Resolved	Urgent	Eliminate cause of Vole-like chirping occurring on most channels when HV wire bias is turned on	Michael Mooney	10/22/2015 12:51 PM
8332	Bug	Closed	High	Add more Wiener channels to archiver	Glenn Horton-Smith	04/13/2015 08:26 PM
8179	Bug	Closed	Normal	On slowmon CSS overview panel, fix order of LSR1, LSR2, PM3, and Cryo racks	Glenn Horton-Smith	04/16/2015 11:03 AM