

uBoone Operations - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
10385	Support	Closed	Normal	Add various things to BEAM subsystem	Glenn Horton-Smith	10/05/2015 03:33 PM
10384	Support	Closed	Normal	Restore low voltage channel 506 (flasher supply) to alarm system	Glenn Horton-Smith	10/06/2015 06:48 PM
10377	Support	Closed	Normal	Adjust rack temperature alarm ranges to be consistent with steady running	Glenn Horton-Smith	10/02/2015 02:01 PM
10376	Support	Closed	Normal	Adjust purity monitor alarm ranges, add new calculations	Glenn Horton-Smith	10/02/2015 02:25 PM