

VME BPM - Issues by Age

#	Tracker	Status	Subject	Created
9358	Task	New	Add nodes to save list	07/02/2015 01:12 PM
9665	Task	New	Move scaling into the frontend	07/17/2015 02:49 PM
10032	Bug	New	VP94 and HP103 show identical data when plotted together	09/03/2015 11:35 AM
10890	Task	Assigned	Upgrade ClassACNet/Mooc	11/09/2015 03:17 PM
11838	Milestone	New	Release 201603A	02/27/2016 09:02 PM
12805	Bug	Resolved	SY BPMs won't boot	05/27/2016 09:33 AM
12809	Bug	New	F4 node won't boot	05/27/2016 02:20 PM
15293	Necessary Maintenance	Resolved	Replace SBC at F4	01/24/2017 11:02 AM
15296	Task	Assigned	BBM Interface	01/24/2017 02:06 PM
16009	Bug	Resolved	Attenuation tables won't initialize correctly on startup	03/28/2017 03:44 PM
16570	Milestone	New	Improvements for auto-tune operation	05/17/2017 10:30 AM
16571	Bug	New	Flat positions being reported intermittently	05/17/2017 10:35 AM
16572	Task	New	Put together a test stand	05/17/2017 10:37 AM
16573	Task	New	Establish alarms for SBPMxx nodes	05/17/2017 10:40 AM
16574	Task	New	ACNET support for beam threshold	05/17/2017 11:05 AM
16575	Task	New	Error state during spill	05/17/2017 11:10 AM
16576	Task	New	Investigate reading back attenuator settings from transition crate	05/17/2017 11:16 AM
16577	Task	New	Improve error handling of CAN bus communication	05/17/2017 11:27 AM