

VME BPM - Unassigned Issues

| # | Project | Tracker | Status | Subject | Author | Updated |
|--------------------|---------|-----------|--------|--|--------------|---------------------|
| VME BPM (8) | | | | | | |
| 16577 | VME BPM | Task | New | Improve error handling of CAN bus communication | John Diamond | 04/12/2018 09:10 AM |
| 16576 | VME BPM | Task | New | Investigate reading back attenuator settings from transition crate | John Diamond | 05/17/2017 11:16 AM |
| 16575 | VME BPM | Task | New | Error state during spill | John Diamond | 05/17/2017 11:10 AM |
| 16574 | VME BPM | Task | New | ACNET support for beam threshold | John Diamond | 05/17/2017 11:05 AM |
| 16573 | VME BPM | Task | New | Establish alarms for SBPMxx nodes | John Diamond | 05/17/2017 10:44 AM |
| 16572 | VME BPM | Task | New | Put together a test stand | John Diamond | 05/17/2017 10:38 AM |
| 16571 | VME BPM | Bug | New | Flat positions being reported intermittently | John Diamond | 05/17/2017 10:36 AM |
| 16570 | VME BPM | Milestone | New | Improvements for auto-tune operation | John Diamond | 05/17/2017 10:30 AM |