

Issues

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated
9023	uBoone Operations	Bug	New	High	investigate high Wiener internal temperatures in PL508 (CrateRails) supplies	Sowjanya Gollapinni	06/03/2015 11:47 AM
10514	uBooNE Detector Physics	Task	New	Normal	Technote: Purity from TPC data	Sowjanya Gollapinni	02/08/2016 11:10 AM
10517	uBooNE Detector Physics	Task	New	Normal	Validating MC analysis technique with data	Sowjanya Gollapinni	02/08/2016 11:04 AM
10516	uBooNE Detector Physics	Task	New	Normal	Analyzing Special Laser and Cosmic Runs at 50, 60, 70kV	Sowjanya Gollapinni	02/08/2016 11:03 AM
10519	uBooNE Detector Physics	Task	New	Normal	Technote: Diffusion Measurement	Sowjanya Gollapinni	02/08/2016 10:58 AM
9036	uBoone Operations	Bug	New	Normal	update the /home/uboone/daq/ directory on glomation-sbc-4	Sowjanya Gollapinni	06/04/2015 12:01 AM
8864	uBoone Operations	Support	New	Normal	Slow Control Monitoring	Sowjanya Gollapinni	05/18/2015 02:08 PM
7248	uBooNE Utilities	Support	New	Normal	Modify metadata extractor to handle json format output from sam_metadata_dumper	Sowjanya Gollapinni	10/31/2014 12:17 PM
7704	uBoone Operations	Necessary Maintenance	Assigned	Normal	Check out the TPC wire bias outputs and set points	Sowjanya Gollapinni	05/14/2015 02:31 PM
8761	uBoone Operations	Necessary Maintenance	Resolved	High	Develop slow monitoring of drift HV current and voltage read back	Sowjanya Gollapinni	10/09/2015 07:08 AM