

VME Intensity Monitor - Task #10788

Milestone # 10928 (Closed): Support for new MI/RR/BNB digitizer firmware

Feature # 10751 (Closed): New MI-RR-BNB Toroid Driver

19751 [5] Correct all startup scripts

11/05/2015 06:28 AM - Roger Tokarek

Status:	Closed	Start date:	11/05/2015
Priority:	Normal	Due date:	11/06/2015
Assignee:	Roger Tokarek	% Done:	0%
Category:		Estimated time:	1.00 hour
Target version:		Spent time:	0.00 hour
Description			
Make sure all calls to adc's and toroids are correct in the startup scripts.			

History

#1 - 11/05/2015 07:42 AM - Roger Tokarek

- Tracker changed from Feature to Task

#2 - 08/02/2016 03:00 PM - Roger Tokarek

- Status changed from New to Closed