

VME Intensity Monitor - Task #12353

Rename ANUB

04/18/2016 02:37 PM - John Diamond

Status:	Assigned	Start date:	04/18/2016
Priority:	Normal	Due date:	
Assignee:	John Diamond	% Done:	0%
Category:	ACNET	Estimated time:	4.00 hours
Target version:		Spent time:	0.00 hour
Description			
First thought for a new name is "MIDCCT"			

History

#1 - 04/21/2016 10:46 AM - Roger Tokarek

Renaming an operational front end requires coordination between Networking and Front End Support. In addition MCR, Main Injector, and Instrumentation Department should be notified before and after the change.

1. Instrumentation Department makes name change request to Networking.
2. Networking confirms with Computing Division and implements the name change.
3. Controls Department FE Support updates its database. Trunk and node stay the same.
4. Instrumentation Department updates the RHOSTS file.

Because ANUB is an operational node these steps must be coordinated to occur in quick succession.