

M3 IPM - Bug #18755

Plotting Charge, Sigma and Turns does not scale to # Turns Analyzed.

01/19/2018 09:25 AM - Denton Morris

Status:	New	Start date:	01/19/2018
Priority:	Normal	Due date:	
Assignee:	Elliott McCrory	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Description			
Plotting for Charge, Sigma and Position scales axis for # Turns Acquired when showing plotting # Turns Analyzed. See attached examples.			
Recycler H104 IPM Spec 10. Acquiring 4000 turns, analyzing 1000 turns, 3000 turns and 4000 turns.			

Files

2018-01-19.09.18.17.060.png	73.4 KB	01/19/2018	Denton Morris
2018-01-19.09.17.51.868.png	9.76 KB	01/19/2018	Denton Morris
2018-01-19.09.17.34.339.png	74.3 KB	01/19/2018	Denton Morris
2018-01-19.09.17.25.426.png	9.8 KB	01/19/2018	Denton Morris
2018-01-19.09.16.53.097.png	9.78 KB	01/19/2018	Denton Morris
2018-01-19.09.17.14.346.png	76 KB	01/19/2018	Denton Morris