

adinstbpm - Task #20683

Milestone # 20540 (New): Booster BPM deployment

Change node name for all BBPM15 devices

08/26/2018 03:07 PM - John Diamond

| | | | |
|------------------------|--------------|------------------------|------------|
| Status: | Resolved | Start date: | 08/26/2018 |
| Priority: | Normal | Due date: | |
| Assignee: | John Diamond | % Done: | 100% |
| Category: | | Estimated time: | 0.00 hour |
| Target version: | | Spent time: | 1.00 hour |
| Description | | | |

History

#1 - 08/26/2018 09:22 PM - John Diamond

- Status changed from New to Resolved

- Assignee set to John Diamond

- % Done changed from 0 to 100

BBPM15 devices re-assigned to BBPL15. DABEL output:

```
clx50$ dabel bbpm15-modify.dbl modify --stdout
! DABEL V8.05 running on file bbpm15-modify.dbl
!
Device B:15COH1      modified successfully
      but no changes detected for some device MODS
Device B:15CORP      modified successfully
Device B:15FLH1      modified successfully
Device B:15HOFF      modified successfully
Device B:15QFLS      modified successfully
Device B:15QORB      modified successfully
Device B:B15NUM      modified successfully
Device B:HP15L       modified successfully
Device B:HP15S       modified successfully
Device B:HP16L       modified successfully
Device B:HP16S       modified successfully
Device B:HP17L       modified successfully
Device B:HP17S       modified successfully
Device B:HST15L      modified successfully
Device B:HST15S      modified successfully
      but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
      Device(s) include:      B:HST15L
Device B:HST16L      modified successfully
      but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
      Device(s) include:      B:HST15L      and B:HST15S
Device B:HST16S      modified successfully
      but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
      Device(s) include:      B:HST15L      and B:HST15S
Device B:HST17L      modified successfully
      but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
      Device(s) include:      B:HST15L      and B:HST15S
Device B:HST17S      modified successfully
      but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
      Device(s) include:      B:HST15L      and B:HST15S
Device B:VP15L       modified successfully
Device B:VP15S       modified successfully
      but duplicate SSDN devices found for property(s):
      PRREAD
```

```
Device(s) include:      B:HP15S
Device B:VP16L          modified successfully
Device B:VP16S          modified successfully
Device B:VP17L          modified successfully
Device B:VP17S          modified successfully
Device B:VST15L         modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
Device(s) include:      B:HST15L      and B:HST15S
Device B:VST15S         modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
Device(s) include:      B:HST15L      and B:HST15S
Device B:VST16L         modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
Device(s) include:      B:HST15L      and B:HST15S
Device B:VST16S         modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
Device(s) include:      B:HST15L      and B:HST15S
Device B:VST17L         modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
Device(s) include:      B:HST15L      and B:HST15S
Device B:VST17S         modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
Device(s) include:      B:HST15L      and B:HST15S
!
! Database modified with following statistics:
!      31 devices modified
!
!**duplicate SSDN properties found
The file stdout does not exist.
```

#2 - 08/28/2018 10:01 AM - John Diamond

- Subject changed from Change node name for all BBPL15 devices to Change node name for all BBPM15 devices