

## adinstbpm - Task #20683

Milestone # 20540 (New): Booster BPM deployment

### Change node name for all BBPM15 devices

08/26/2018 03:07 PM - John Diamond

<b>Status:</b>	Resolved	<b>Start date:</b>	08/26/2018
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>	John Diamond	<b>% Done:</b>	100%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>		<b>Spent time:</b>	1.00 hour
<b>Description</b>			

#### History

##### #1 - 08/26/2018 09:22 PM - John Diamond

- Status changed from New to Resolved
- Assignee set to John Diamond
- % Done changed from 0 to 100

BBPM15 devices re-assigned to BBPL15. DABEL output:

```
clx50$ dabel bbpm15-modify.dbl modify --stdout
! DABEL V8.05 running on file bbpm15-modify.dbl
!
Device B:15COH1      modified successfully
      but no changes detected for some device MODS
Device B:15CORP      modified successfully
Device B:15FLH1      modified successfully
Device B:15HOFF      modified successfully
Device B:15QFLS      modified successfully
Device B:15QORB      modified successfully
Device B:B15NUM      modified successfully
Device B:HP15L       modified successfully
Device B:HP15S       modified successfully
Device B:HP16L       modified successfully
Device B:HP16S       modified successfully
Device B:HP17L       modified successfully
Device B:HP17S       modified successfully
Device B:HST15L      modified successfully
Device B:HST15S      modified successfully
      but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
      Device(s) include:      B:HST15L
Device B:HST16L      modified successfully
      but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
      Device(s) include:      B:HST15L      and B:HST15S
Device B:HST16S      modified successfully
      but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
      Device(s) include:      B:HST15L      and B:HST15S
Device B:HST17L      modified successfully
      but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
      Device(s) include:      B:HST15L      and B:HST15S
Device B:HST17S      modified successfully
      but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
      Device(s) include:      B:HST15L      and B:HST15S
Device B:VP15L       modified successfully
Device B:VP15S       modified successfully
      but duplicate SSDN devices found for property(s):
      PRREAD
```

```

Device(s) include:      B:HP15S
Device B:VP16L          modified successfully
Device B:VP16S          modified successfully
Device B:VP17L          modified successfully
Device B:VP17S          modified successfully
Device B:VST15L         modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
Device(s) include:      B:HST15L      and B:HST15S
Device B:VST15S         modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
Device(s) include:      B:HST15L      and B:HST15S
Device B:VST16L         modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
Device(s) include:      B:HST15L      and B:HST15S
Device B:VST16S         modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
Device(s) include:      B:HST15L      and B:HST15S
Device B:VST17L         modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
Device(s) include:      B:HST15L      and B:HST15S
Device B:VST17S         modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
Device(s) include:      B:HST15L      and B:HST15S
!
! Database modified with following statistics:
!      31 devices modified
!
!**duplicate SSDN properties found
The file stdout does not exist.

```

**#2 - 08/28/2018 10:01 AM - John Diamond**

- Subject changed from Change node name for all BBPL15 devices to Change node name for all BBPM15 devices