

## adinstbpm - Task #20705

Milestone # 20540 (New): Booster BPM deployment

### Change node name for all BBPM24 devices

08/28/2018 08:06 PM - John Diamond

<b>Status:</b>	Resolved	<b>Start date:</b>	08/28/2018
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>	John Diamond	<b>% Done:</b>	100%
<b>Category:</b>		<b>Estimated time:</b>	2.00 hours
<b>Target version:</b>		<b>Spent time:</b>	0.00 hour
<b>Description</b>			

#### History

##### #1 - 08/28/2018 09:29 PM - John Diamond

- Status changed from Work in progress to Resolved

- % Done changed from 0 to 100

Re-assigned all B: devices on BBPM24 to BBPL24. DABBEL output -

```
clx50$ dabbel bbpm24-modify.dbl modify --stdout
! DABBEL V8.05 running on file bbpm24-modify.dbl
!
Device B:24BPMN      modified successfully
Device B:24COH1     modified successfully
Device B:24CORP     modified successfully
Device B:24FLH1     modified successfully
Device B:24HOFF     modified successfully
Device B:24QFLS     modified successfully
Device B:24QORB     modified successfully
Device B:B24NUM     modified successfully
    but duplicate SSDN devices found for property(s):
    PRREAD
    Device(s) include:      B:24BPMN
Device B:HP01L      modified successfully
Device B:HP01S      modified successfully
Device B:HP02L      modified successfully
Device B:HP02S      modified successfully
Device B:HP03L      modified successfully
Device B:HP03S      modified successfully
Device B:HP04L      modified successfully
Device B:HP04S      modified successfully
Device B:HP05L      modified successfully
Device B:HP05S      modified successfully
Device B:HP24L      modified successfully
Device B:HP24S      modified successfully
Device B:HST01L     modified successfully
Device B:HST01S     modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
    Device(s) include:      B:HST01L
Device B:HST02L     modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:HST02S     modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:HST03L     modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:HST03S     modified successfully
```

```

    but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:HST04L      modified successfully
    but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:HST04S      modified successfully
    but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:HST05L      modified successfully
    but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:HST05S      modified successfully
    but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:HST24L      modified successfully
    but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:HST24S      modified successfully
    but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:VP01L      modified successfully
Device B:VP01S      modified successfully
Device B:VP02L      modified successfully
Device B:VP02S      modified successfully
Device B:VP03L      modified successfully
Device B:VP03S      modified successfully
Device B:VP04L      modified successfully
Device B:VP04S      modified successfully
Device B:VP05L      modified successfully
Device B:VP05S      modified successfully
Device B:VP24L      modified successfully
Device B:VP24S      modified successfully
Device B:VST01L     modified successfully
    but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:VST01S     modified successfully
    but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:VST02L     modified successfully
    but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:VST02S     modified successfully
    but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:VST03L     modified successfully
    but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:VST03S     modified successfully
    but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:VST04L     modified successfully
    but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:VST04S     modified successfully
    but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:VST05L     modified successfully
    but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S

```

```
Device B:VST05S      modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:VST24L      modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
Device B:VST24S      modified successfully
    but duplicate SSDN devices found for property(s):
    PRBCTL PRBSTS
    Device(s) include:      B:HST01L      and B:HST01S
!
! Database modified with following statistics:
!      56 devices modified
!
!**Fast_FTD_Noted: device with rate > 1 Hz
!
!**duplicate SSDN properties found
The file stdout does not exist.
```