

**PIP-II IT HWR - Bug #25134**

**Move Beam Sync button on LV to the Controls page and the Cav Sim button to an expert's page.**

10/27/2020 09:37 AM - Shrividhyaa Sankar Raman

<b>Status:</b>	New	<b>Start date:</b>	10/27/2020
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>		<b>% Done:</b>	0%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>		<b>Spent time:</b>	0.00 hour
<b>Description</b>			
Move Beam Sync button on LV to the Controls page and the Cav Sim button to an expert's page.			