

Erlang Front-end Framework - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
24980	Feature	New	Normal	Expand alarm reporting to indicate reading errors.		09/18/2020 03:26 PM
24938	Bug	New	Normal	Gracefully handle ACNET startup errors.		09/09/2020 03:51 PM
24267	Feature	New	Normal	Central respository/database for Erlang Alarm reports		04/04/2020 02:05 PM
23957	Support	Assigned	Normal	Bad device in config	Dennis Nicklaus	01/27/2020 11:12 AM
23110	Feature	New	Normal	Request for 15Hz readout of one MFTU segment	Dennis Nicklaus	08/13/2019 12:09 PM
22702	Bug	Assigned	Normal	Problem with LLRF OTSDaq interface process not dying	Dennis Nicklaus	06/07/2019 05:22 PM
21808	Support	New	Normal	Make the camera server C software less verbose		01/30/2019 02:38 PM
21796	Bug	Assigned	Normal	ps_lxi_driver problems with init -- undef	Richard Neswold	01/30/2019 01:29 PM
21725	Feature	Work in progress	Normal	Create an ACNET interface for NWA Omega PID temperature controllers	Dennis Nicklaus	03/19/2019 04:55 PM
21724	Feature	New	Normal	Create driver to receive image summary data from IOTA cameras	Dennis Nicklaus	01/18/2019 03:22 PM
21708	Bug	Assigned	Urgent	LXI PS Driver is occasionally returning [57 -107] when setting	Richard Neswold	02/04/2019 01:19 PM
21672	Bug	Feedback	High	ps_lxi_driver downloads problem at startup, alarms fail	Richard Neswold	10/25/2019 12:42 PM
21493	Bug	Assigned	Normal	iota_magnet_comb_drv repeatedly crashes	Jianming You	12/06/2018 11:26 AM
21492	Bug	New	Normal	When dev_registry restarts all drivers because one driver crashes too much, settings don't get downloaded		12/06/2018 05:04 PM
21414	Feature	Assigned	Normal	Add write-read atomic operation for CEC protocol	Dennis Nicklaus	04/15/2019 05:57 PM
21333	Feature	New	Normal	Possible improvements to mk_acsysfe script.	Richard Neswold	11/08/2018 11:30 AM
20622	Feature	Assigned	Normal	gpib_drv should have a way of not waiting on a reply for commands that have no expected reply	Jerry Firebaugh	09/17/2019 03:19 PM
20617	Bug	Assigned	Normal	Fix remaining issues with SG power supplies	Richard Neswold	11/21/2018 03:29 PM
18476	Feature	New	Normal	Migrate Serial-to-Ethernet Devices from VxWorks to Erlang		12/05/2017 02:45 PM
18118	Bug	Feedback	Normal	copyset localapp dpmclient disconnects sometimes don't reconnect automatically.	Dennis Nicklaus	11/30/2018 02:16 PM
16195	Support	New	Normal	Make the framework more control system agnostic		08/15/2018 02:55 PM
15600	Feature	New	Normal	Ideas for erlang front-end monitoring.		03/12/2019 09:32 AM
14805	Bug	Assigned	Normal	erl-modbus device occasionally see long delays	Dennis Nicklaus	11/21/2018 02:53 PM
13798	Feature	New	Normal	Allow front-end to connect to multiple local aliases		11/21/2018 02:49 PM
13617	Feature	New	Normal	New driver: setting forwarder		08/22/2016 04:10 PM
10769	Feature	New	Normal	Switch data collection to use graphs		08/15/2018 02:57 PM
7839	Feature	New	Normal	Add IOC support		08/15/2018 02:57 PM