

## inst-bpm - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
9636	Bug	Assigned	Normal	Timing board stops generating TCLK interrupts	John Diamond	11/24/2015 02:23 PM
9613	Bug	Resolved	Normal	btimemod_device_release does not release alarm interrupt handler	John Diamond	07/14/2015 09:55 AM
9280	Bug	New	Normal	Turn off interrupts when module is removed.	John Diamond	06/23/2015 01:55 PM
9088	Bug	New	Low	BPMDRO does not release on exit	John Diamond	06/10/2015 11:04 AM