

## inst-bpm

	2021-3				2021-4				2021-5				2021-6				2021-7				2021-8							
	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34		
<b>AD Instrumentation</b>	<b>AD Instrumentation</b>																											
<b>inst-bpm</b>																												
Refactor pointer usage to smart pointers	Accepted																											
Booster frequency curve	Accepted																											
State Machine subsystem	Accepted																											
Implement timer-triggered commands	New																											
Instrument bpmd control commands (...)	New																											
BPM DRO does not release on exit	New																											
adc250x12xs VXS interface	New																											
StateMachine refactor	New																											
Design ACNET interface for command (...)	New																											
Use the GoF State pattern in StateMachine (...)	New																											
Move the Command and CommandList (...)	New																											
Rename the IDLE command the EXIT (...)	New																											
Turn off interrupts when module is removed.	New																											
Execute CommandLists	Assigned																											
Find a replacement for the CT VX405/04x (...)	New																											
Down Converter Test	New																											
bpmcli command for loading the (...)	New																											
Test command list for reading out (...)	New																											
Make Synoptic pages for displaying (...)	Feedback																											
Timing board stops generating TCLK (...)	Assigned																											
btimemod_device_release does not release (...)	Resolved																											
State Machine subsystem test	New																											
PXIE BPM Deployment	New																											
PXIE BPM Test Node	New																											
Network connection and kerberos (...)	Assigned																											
Boot flash for PXIE BPM test (...)	New																											