

MI/RR IPM

	2021-1				2021-2				2021-3					2021-4				2021-5					2021-6				
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25		
AD Instrumentation	AD Instrumentation																										
MI/RR IPM																											
Single turn plot does not work when (...)	New																										
Necessary LabView parameters are no (...)	Resolved																										
State machine devices for Booster IPMs	Resolved																										
Plotting Charge, Sigma and Turns does (...)	New																										
Single turn plot not showing current (...)	Resolved																										
Excessive delay in first plot, capturing (...)	New																										