

## Recycler Tune Control Application (PA4208, R2) - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
14742	Feature	Accepted	High	Setting dqH and dqV to zero should put 0 current on 30 quad trims		12/01/2016 03:03 PM
11821	Feature	New	Low	New phase trombone		12/01/2016 03:04 PM
8389	Bug	New	Normal	Tune setting should fail when any corrector reaches its current limit		04/21/2015 04:23 PM
8303	Idea	New	Normal	Beam-Compensation current limit		04/11/2015 10:02 PM