

## uBoone Operations - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
10385	Support	Closed	Normal	Add various things to BEAM subsystem	Glenn Horton-Smith	10/05/2015 03:33 PM
10384	Support	Closed	Normal	Restore low voltage channel 506 (flasher supply) to alarm system	Glenn Horton-Smith	10/06/2015 06:48 PM
10377	Support	Closed	Normal	Adjust rack temperature alarm ranges to be consistent with steady running	Glenn Horton-Smith	10/02/2015 02:01 PM
10376	Support	Closed	Normal	Adjust purity monitor alarm ranges, add new calculations	Glenn Horton-Smith	10/02/2015 02:25 PM
8864	Support	New	Normal	Slow Control Monitoring	Sowjanya Gollapinni	05/18/2015 02:08 PM
8862	Support	Accepted	Normal	Laser Monitoring	Matthias Luethi	05/19/2015 10:14 AM
8861	Support	Resolved	Normal	HV Monitoring	Sarah Lockwitz	10/09/2015 07:08 AM
8860	Support	Resolved	Normal	DAQ Monitoring	Wesley Ketchum	10/09/2015 07:09 AM
8859	Support	New	Normal	Cryogenics Monitoring	Ben Carls	05/18/2015 01:54 PM
8858	Support	New	Normal	Calibration Monitoring	Ben Carls	05/18/2015 01:52 PM
8857	Support	New	Normal	Beam Monitoring	Tia Miceli	05/18/2015 01:51 PM