

## VME Drivers - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
23501	Support	Assigned	Normal	Install 4 more V474 cards in MC1HRM	Richard Neswold	10/31/2019 02:43 PM
11530	Feature	Assigned	Low	The V474 driver needs to support degaussing magnets	Richard Neswold	04/13/2018 03:10 PM