

VME Intensity Monitor - Issues by Age

#	Tracker	Status	Subject	Created
8559	Feature	New	BBB standard deviation device	05/01/2015 09:15 AM
8558	Bug	Feedback	BBB devices are returning stale data	05/01/2015 09:14 AM
10199	Task	Assigned	Refactor to use the PMCUCDTimingSystem class from the timing library	09/20/2015 09:38 PM
9391	Feature	Assigned	Implement MDAT Receiver	07/07/2015 03:08 PM
10262	Task	Assigned	Configure MDAT frames	09/23/2015 09:47 AM
10966	Feature	Assigned	Reset sum on disarm event + delay	11/19/2015 04:06 PM
10946	Task	Resolved	ACNET settings for ADC parameters	11/17/2015 01:46 PM
10985	Feature	Assigned	Injection and Extraction Cycle Devices	11/23/2015 03:08 PM
11028	Task	New	Support beam before extraction sample	11/30/2015 04:38 PM
11011	Feature	Assigned	Normalized BEL devices	11/26/2015 11:13 AM
11019	Milestone	Accepted	Cycle devices for anub	11/28/2015 09:48 PM
11021	Feature	Assigned	Use Trace for logging & error reporting	11/29/2015 08:58 AM
9396	Feature	Assigned	Beam Energy Loss Devices	07/07/2015 03:19 PM
10477	Milestone	New	ANUB Startup	10/10/2015 09:30 AM
11520	Task	Assigned	Create new sum devices	01/27/2016 02:06 PM
11946	Bug	New	Scale Factor EVENT OVERLAP Error Message	03/11/2016 03:44 PM
11687	Task	New	Move ADC drivers to adinsthw	02/09/2016 12:26 PM
11629	Task	New	Refactor to useAD/Control's concurrency library	02/04/2016 09:34 AM
11849	Feature	Assigned	TSG Support	03/01/2016 02:18 PM
11891	Task	Assigned	Support Alexei's changes to the DCCT firmware	03/03/2016 09:30 PM
12190	Milestone	New	Turn of tracing for ACNET tasks	04/06/2016 04:10 PM
12191	Task	New	Refactor TRACE0 calls with the appropriate TRACE/TRACE0/TRACEP	04/06/2016 04:13 PM
12352	Milestone	Assigned	Transition operational Recycler DCCT devices to ANUB	04/18/2016 02:36 PM
12353	Task	Assigned	Rename ANUB	04/18/2016 02:37 PM
12513	Support	New	Array Data Timeout Request	05/04/2016 02:50 PM
12616	Support	New	Transfer MI DCCT Acnet devices from ANUB to MIDCCT	05/12/2016 02:04 PM
12632	Feature	Resolved	Support new digitizer gate mode for ASTA	05/13/2016 09:39 AM
12935	Support	Assigned	DCCT: Transfer Recycler Devices from MIBEAM to ANUB	06/15/2016 04:40 PM
13070	Task	Assigned	Support different DcctDrv firmware running on ANUB and MIDCCT	06/29/2016 12:57 PM
13359	Support	Work in progress	Update Pxie Gate Width Calibration Mode	07/27/2016 04:25 PM
9524	Task	Work in progress	Request remote reboot devices	07/10/2015 10:00 AM

#	Tracker	Status	Subject	Created
10475	Task	Work in progress	Simplify Script Set Register Functions	10/09/2015 06:24 PM
10975	Task	Work in progress	Acnet Device Set Toroid ADC Registers S60, MI10, MI14, MI30	11/22/2015 11:56 AM
11737	Support	Work in progress	Rename *.h Files to *.hpp	02/16/2016 09:50 AM
11758	Support	Work in progress	201602A Document ATR	02/18/2016 10:05 AM
11996	Bug	Work in progress	Remove Conditional Compilation for Addressing	03/20/2016 05:52 PM
12609	Milestone	Assigned	MI/RR DCCT Configuration Update	05/12/2016 01:05 PM
12749	Bug	Work in progress	Cleanup DcctDrv & Calls to DcctDrv	05/23/2016 09:28 AM
12944	Milestone	New	New DCCT V2.1 Firmware Driver	06/16/2016 04:21 PM
12865	Support	Work in progress	Pxint Firmware Update to ABB0E	06/06/2016 05:28 PM
12929	Bug	Work in progress	Pxie Scrapers Clean Up	06/14/2016 02:33 PM
13371	Support	New	Replicate PXINT on NBEAM Request	07/29/2016 09:20 AM
13694	Feature	Assigned	Support tracking the chopper's pulse width with a static amount of extra time	08/26/2016 10:52 AM
13919	Task	Assigned	Fix scaling for ring pick MPS thresholds	09/23/2016 10:46 AM
13962	Task	Assigned	ADC configuration commands for PXIE Toroids	09/28/2016 10:48 AM
13918	Task	Assigned	Configure second ring pickup for PXIE	09/23/2016 10:07 AM
12946	Feature	New	MDAT requires Baseline Filter	06/16/2016 04:42 PM
11729	Feature	Work in progress	201602A Replace Latch with ATR	02/15/2016 02:49 PM
10976	Feature	Work in progress	Confirm ADC Present and Correct	11/22/2015 01:28 PM
13572	Feature	Assigned	ACNET device support for new MPS features in ABB0F firmware	08/17/2016 01:37 PM
14280	Task	Assigned	BBM for R:TOR703	10/26/2016 10:22 AM
14283	Task	Assigned	Configure pulse width tracking for PXIE scrapers	10/26/2016 10:48 AM
14359	Task	Assigned	Write integrated pulse readings to file	11/02/2016 12:08 PM
14446	Task	Work in progress	New scale factors for PXIE Ring Pickups 1 & 2	11/08/2016 02:58 PM
14512	Task	Assigned	Support for Rich's MPS transmission loss task	11/15/2016 04:36 PM
14696	Task	Assigned	Support for PXIE digitizer firmware ABC02	11/29/2016 09:00 AM
15051	Task	New	Request for I:13SUM1	01/09/2017 02:20 PM
15282	Bug	New	Support plotting MDAT transmitter frames via ACNET	01/23/2017 02:13 PM
15979	Task	Work in progress	Create devices for Ring Pickup study at PXIE	03/27/2017 02:03 PM
16023	Task	Assigned	Configure R:TOR703 for g-2 operation	03/29/2017 09:21 PM
16050	Feature	Assigned	Build support into Cycle Devices that can support the two groups of 8 for g-2 transfers	04/03/2017 01:58 PM
16045	Task	Resolved	Configure a cycle device for R:TOR703 g-2 operation	04/03/2017 10:36 AM
16589	Task	New	Verify new devices with a test signal	05/18/2017 02:51 PM
16590	Task	New	Verify BBM interface with Bill Marsh's test program	05/18/2017 02:52 PM

#	Tracker	Status	Subject	Created
16784	Task	Resolved	Commission new scrapers for PXIE	06/08/2017 09:04 AM
16533	Task	Work in progress	Create ACNET devices for new toroids	05/15/2017 02:00 PM
16532	Task	Work in progress	Install hardware for NMLTR3	05/15/2017 01:59 PM
16524	Milestone	New	Commission new toroid nodes at NML	05/15/2017 01:44 PM
16531	Task	Work in progress	Install hardware for NMLTR2	05/15/2017 01:59 PM
17355	Task	New	Test & Verify	08/03/2017 09:40 AM
17344	Task	Assigned	ACNET devices for new scrapers at PIP2IT	08/02/2017 08:27 PM
17350	Task	Resolved	Configure M40TOR CPU board	08/03/2017 09:20 AM
17351	Task	Resolved	Request ACNET node ID assignment for M40TOR	08/03/2017 09:23 AM
17352	Task	Assigned	Configure startup script	08/03/2017 09:29 AM
17764	Task	New	More summation devices requested	09/22/2017 03:59 PM
15052	Task	New	Sum device for muon campus toroid (R:TOR703)	01/09/2017 02:24 PM
19614	Task	New	Install and configure hardware for S16TOR	04/09/2018 03:10 PM
19613	Milestone	Assigned	Commission F16TOR	04/09/2018 03:09 PM
11965	Milestone	New	April Release - 201604A	03/15/2016 12:19 PM
9392	Task	Resolved	Deploy New MI Toroid Nodes	07/07/2015 03:10 PM
9388	Milestone	New	2015 Shutdown	07/07/2015 03:00 PM
17354	Task	New	Configure MDAT transmitter	08/03/2017 09:38 AM
17345	Milestone	New	Comission M40TOR front end	08/02/2017 09:26 PM
23796	Task	Assigned	E:NUMIPWR	12/23/2019 09:05 AM