

Neutrino Division LArTPC Test Stands - Task #16083

Investigate chattering solenoid valve on Tall Bo

04/04/2017 04:40 PM - Kathrine Cipriano

Status:	New	Start date:	04/04/2017
Priority:	Low	Due date:	
Assignee:	Kathrine Cipriano	% Done:	0%
Category:	TallBo	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Description			
Stephen thinks it might stem from a problem with the control system, or it might not have a deadband. Look into it.			