

Main Injector and MRF - Task #24171

MI PHIS Front End Repair

03/11/2020 05:10 PM - Philip Varghese

Status:	New	Start date:	03/11/2020
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Description			
The MI PHIS front end unit #1 was removed from rack MI60014 and the spare unit #2 was installed in its place. Unit #1 was found to have a failed 24V power supply - ACOPIAN model A24MT350. The power supply needs to be replaced and all power supplies checked. The failed unit is located in the cabinets behind the racks in the MI-60 control room.			

History

#1 - 03/13/2020 08:14 AM - Daniel Klepec

There are 2 Acopian model A24MT350 power supplies in stock. No need to order.