

## PIP II IT SSR1 - Task #25327

### SSR1 Resonance Controller Installation

12/16/2020 02:54 PM - Daniel Klepec

<b>Status:</b>	Resolved	<b>Start date:</b>	12/16/2020
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>	Daniel Klepec	<b>% Done:</b>	100%
<b>Category:</b>	SSR1 Resonance Control	<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>		<b>Spent time:</b>	20.00 hours
<b>Description</b>			
Both RCCA and RCCB are both installed. Links between SOCMFC's and RCC's have been routed and connected. The spreadsheet of the resistance and capacitance measurements between the pairs is attached.			

#### History

#1 - 01/27/2021 11:54 AM - Shrividhya Sankar Raman

- Status changed from Assigned to Resolved

#### Files

SSR1 Piezo Cable Measurements.xlsx	10.7 KB	12/16/2020	Daniel Klepec
------------------------------------	---------	------------	---------------